


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-121	Smoke	10/20/2008	ADS/TM	S0700_020MH	Dry	Yes	1,105.18



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-121	Smoke	10/20/2008	ADS/TM	S0700_020MH	Dry	Yes	1,105.18

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S0700_032G1	S0700_032UN	S0700_031UN	9.809363	8
S0900_013G1	S0900_013MH	S0900_001MH	221.4014	8
S0900_034G1	S0900_034MH	S0900_013MH	201.0673	8
S0700_031G1	S0700_031UN	S0900_001MH	104.3183	8
S0900_001G1	S0900_001MH	S0900_024MH	184.8787	8
S0900_045G1	S0900_045DE	S0700_020MH	129.5475	8
S0700_030G1	S0700_030DE	S0700_020MH	165.3062	8
S0700_020G1	S0700_020MH	S0700_032UN	88.85325	8

Observations & Photos

Obs_ID S1028-121-OB01

Address 3432 Piedmont Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S0700_020MH

Comments Smoke from cleanout in front yard. 3432 Piedmont Ave.



Picture \S1028-121-OB01-P01.jpg

Comments Front of house, 3432 Piedmont Ave.

Obs_ID S1028-121-OB02

Address 3437 Piedmont Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S0900_001MH

Comments Smoke from cleanout in back yard. 3437 Piedmont Ave.



Picture \S1028-121-OB02-P01.jpg

Comments Back of house, 3437 Piedmont Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-121	Smoke	10/20/2008	ADS/TM	S0700_020MH	Dry	Yes	1,105.18

Obs_ID S1028-121-OB03

Address 3435 Piedmont Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S0900_001MH

Comments Smoke from cleanout in back yard. 3435 Piedmont Ave.



Picture \S1028-121-OB03-P01.jpg

Comments Back of house, 3435 Piedmont Ave.

Obs_ID S1028-121-OB05

Address 3417 Piedmont Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S0900_013MH

Comments Smoke from cleanout in back yard. 3417 Piedmont Ave.



Picture \S1028-121-OB05-P01.jpg

Comments Back yard, 3417 Piedmont Ave.

Obs_ID S1028-121-OB04

Address 3425 Piedmont Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S0900_013MH

Comments Smoke from cleanout in back yard. 3425 Piedmont Ave.



Picture \S1028-121-OB04-P01.jpg

Comments Back of house, 3425 Piedmont Ave.

Obs_ID S1028-121-OB06

Address 3407 Piedmont Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S0900_034MH

Comments Smoke from cleanout in back yard. 3407 Piedmont Ave.



Picture \S1028-121-OB06-P01.jpg

Comments Back of house, 3407 Piedmont Ave.